Date: April 19, 2021

Alhamrani Universal Co on behalf of Alinma Bank

4th Floor South Motoon Tower, Prince Mohammed bin Abdulaziz St., Riyadh 12212, Saudi Arabia

Letter of Confirmation for
Contactless IC Terminal Check for Implementation(TCI-CL)

We confirm that the following terminal has passed TCI-CL in accordance with TCI-CL Procedure.
Please be noted that the tested product below must be retested when:
➤ IFM or Kernel is modified.
➤ Proprietary Application that affects IC card processing is modified.
➤ Contactless Reader is modified.
➤ An interoperability issue that affects JCB card acceptance is fixed.
➤ JCB requests a retest.

Submission Date: April 15, 2021
Test Version: 1.30
Reference Number: AAlh210404115357
Tested Terminal:

IFM Manufacturer Company Name	Ingenico terminals
EMVCo Level 1 Approval Number	13114 0814 400 21 FIM
Kernel Manufacturer Company Name	Ingenico terminals
EMVCo Level 2 Approval Number	2-04683-1-1C-FIME-0420-4.3i 2-04683-1-1OS-FIME-0420-4.3i
Proprietary Application Name (Version)	T3.EMV.Contact Version 09.04

Contactless Reader:

Select your Level 2 Approval Test (Contactless)	JCB Level 2 Approval Number (Contactless)
Level 2 Approval Number (Contactless)	19PF16-055-08
Reader Manufacturer Company Name	Ingenico Terminals
Contactless Reader Name	Move/2500

No Warranty and No Liability:
Even though the test results have met JCB requirements, JCB provides no warranty of any kind for the tested terminals. Also, JCB is not responsible for any damages caused by the test.

Note on Selecting and Setting-up Terminals:
1. To prevent interoperability issues, we recommend that the Acquirer select terminals that have been certified as compliant with the latest EMV specifications. The risk of interoperability issues is higher with terminals compliant only with older EMV specifications. You may find information about the latest EMV specifications on the EMVCo web site. An "Issues List" of known interoperability issues is also published on the EMVCo web site   http://www.emvco.com/

2. For proper processing of JCB cards, the terminal must be properly set up. In particular:
    - Do not set Cirrus AID
    - Load the CAPK properly

Sincerely,

Masao Noda

Masao Noda
Senior Vice President
Brand Infrastructure & Technologies Department II
JCB Co., Ltd.